


FACTS AND FIGURES



Damage Grade (1-2)
674

Damage Grade (3-5)
2,358

Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	91.52%	53.21%
Timber Frame Structure	7.45%	25.88%
Bamboo	0.86%	3.70%
Brick and Cement Mortar Masonry	0.07%	10.51%
Others	0.09%	6.70%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	2,247
PA Agreement	2,247
I st Tranche received	2,166 81
II nd Tranche received	1,927 320
III rd Tranche received	1,525 722

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	533
PA Agreement	533
I st Tranche received	435 98
II nd Tranche received	533

Grievances

Registered: -

Addressed: -

Non-compliances

Registered: 16

Addressed: 4

Data Updated on: 2019-08-31 00:00:00

PO Presence

Active: No POs Reported

Phased Out: CW (DRM), CW (Education), CW (Livelihood), CW (Shelter), FCA (Education), HELVETAS (Shelter)

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	7,587	-	1,500
Aggregate	m ³	5,724	-	1,500
Sand	m ³	793	-	2,500
Timber	cu. ft.	851	-	-
Cement (PPC)	Sack	-	-	1,050
Cement (OPC)	Sack	20,745	-	1,150
Rebars	kgs.	87,275	-	84
Tin	bundle	853	-	-
Bricks	pcs.	447,226	-	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

- / -
- / -

OTHER SECTORS



Schools

Damaged: 39
Under Construction: 17
Construction Completed: 17



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

KEY CONTACTS

Municipal Office

Jagat Bdr. Bholan
Chair Person
9744035699

Municipal Office

Sanjeev Kumar Sah
Focal Person
9849669417

Municipal Office

Durga Devi Sunuwar
Deputy Chair Person
9840583865

DLPIU-GMaLI

Surya Prakash Bista
DLPIU-Chief
9843208907

Municipal Office

Sanotsh Nepali
Chief Administration Officer
9854041892

DLPIU-Building

Prabhakar Lal Karna
DLPIU-Chief
9854041543

HHs WITH LAND ISSUES

No Reported Land Issues


STATUS OF TECHNICAL STAFF

Staff	Available Nos.	Additional Req. Nos.
Engineers	3	-
Sub-Engineers	5	-
Asst. Sub-Engineers	4	-
Masons	- (7 days) - (50 days)	- (7 days) - (50 days)

Source: Municipal survey


MASON TRAINING

Trainings (# out of total required)



Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information

1. Prabin Gautam (General Coordinator) 9860687776	2. Tulasi Ram Lamichhane (Technical Coordinator) 9851213610	3. Pranjal Singh Bhandari (Information Management Officer) 9840057752
--	--	--